


Wipes Dispenser may be mounted on a horizontal surface or a vertical surface. See *Illustrations 1 and 2*.







Mounting Instructions Using Bolts and Nuts (PREFERRED METHOD)

- 1. Place Wipes Dispenser on top of Waste Container Dome Lid. Using the Dispenser as a guide, mark the hole locations. See Illustration 1
- 2. Drill 0.2" Diameter holes into the mounting surface at the locations marked in Step 1
- 3. Insert bolts through the existing holes on the dispenser and through the drilled holes on the mounting surface.
- 4. Thread the nuts on the opposite side of the bolt and tighten. See Illustration 3

Mounting Instructions Using Screws and Wall Anchors

- 1. Place Wipes Dispenser against desired mounting surface. Using the Dispenser as a guide, mark the hole locations.
- 2. Drill 0.2" Diameter holes into the mounting surface at the locations marked in Step 1 $\,$
- 3. Insert wall anchors into the holes
- 4. Mount dispenser to surface by inserting the screws through the holes on the dispenser and screwing into the anchors.

Mounting Instructions Using Double-Sided Tape

- 1. Clean mounting surfaces with alcohol wipe and allow to air dry
- 2. Remove tape backing and press on the bottom or back of dispenser
- 3. Remove opposite side of tape backing
- 4. Firmly press the adhesive portion of the dispenser onto the mounting surface and hold for 15 seconds



THE BEST TRASH CANS AT THE BEST PRICES